

**CITY OF BALTIMORE WET WEATHER CONSENT DECREE  
SMOKE AND DYED WATER TESTING FORM**

Page 1 of 4

Sewershed: OUTFALL

Company: REI/DRAYCO

Date: 09/29/2008

Test Type: SMOKE

Ground Condition:  
Dry: **X** Damp: \_ Wet: \_


Supervisor: E.R.

Manhole ID: S51KK\_003MH

Test ID: S1039-001

Notifications Made: **X** (Residents, Fire, 311)

Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



[illegible]

CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-001	Date: 09/29/2008	Manhole ID: S53KK_003MH
Defect No: OB01	Supervisor: E.R.	Basin: Outfall
Location: 1700 N. ELLWOOD AVE.		
Source Type: 01 Main Sewer	Sector: 01 Public	
Location: 01 Paved Concrete	Severity: 03 Moderate	Drainage Area: 65 ft <sup>2</sup>
Comments: Smoke is coming from between cracks in concrete between site of orange cone and the foreground of photograph, also extending horizontally across picture to the manhole.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-P01  
Filename: S1039-001\_OB01-P01.jpg

CITY OF BALTIMORE  
SMOKE TESTING OBSERVATION SUMMARY  
OUTFALL SEWERSHED  
BALTIMORE CITY PROJECT 1039  
REI/DRAYCO

Unique Test ID: S1039-001	Date: 09/29/2008	Manhole ID: S51KK_003MH
Defect No: OB02	Supervisor: E.R.	Basin: Outfall
Location: 1720 EDISON HWY.		
Source Type: 03 Cleanout	Sector: 02 Private	
Location: 02 Asphalt	Severity: 03 Moderate	Drainage Area: 1 ft <sup>2</sup>
Comments: Smoke is coming from the cleanout in the rear parkinglot of building.		

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-P01  
Filename: S1039-001\_OB02-P01.jpg